SIERRA WIRELESS PRODUCT BULLETIN

OVERVIEW

DATE ISSUED:	June 17th, 2022	**TRACKING NUMBER:**	4134925
ISSUED BY:	IoT Solutions Product Management		
PRODUCTS AFFECTED:	HL7800, HL7802, RC76xx, WP76xx, WP7702, FX30, GL7611		
SKUS AFFECTED:	All R2C enabled SKUs		
BULLETIN:	Addition of 2nd Source eSIM		
EFFECTIVE DATE:	Effective Immediately		
FOR DISTRIBUTION TO:	Customers and partners		

Details

In order to maintain component supply, Sierra Wireless is announcing the addition of a 2nd source eSIM component to the affected products.

The addition of this 2nd source eSIM component has no impact on the fit, form or function of the module. The eSIM has passed all Engineering qualification and reliability tests. Additionally, no firmware changes are needed to support the new eSIM.

For RC76xx, WP76xx, WP7702, FX30 and GL7611 products, a minor update to the manufacturing test procedure is required to properly read the ICCID of the 2nd source eSIM. This change is implemented in the SKU PRI, as such the PRI version will be incremented. However, aside from the revised SKU PRI name there is no other customer impact; the configuration of the module itself remains unchanged. HL78xx modules do not require any PRI change as a result of the 2nd source eSIM.

Effective Dates

The 2nd source eSIM has been added to the production BOM of the affected SKUs. This will be treated as a rolling change with mixed shipments possible. We will not be able to accommodate any requests for shipments with a specific eSIM.

More information

For more information please contact your Sierra Wireless sales/technical support person.

APPENDIX - Affected R2C SKUs

Product	SKU#	PRI Change Required
HL7800	1104526	No
	1104888	
	1104956	
	1104940	
	1104664	
	1104755	
	1104748	
	1104764	
	1104776	
HL7802	1104503	
	1104845	
	1104889	
	1105030	
	1104569	
RC7611	1104595	Yes
	1104691	
	1104917	
	1104920	
	1104921	
	1104942	
RC7611-1	1104617	
	1104692	
	1104740	
	1104777	
	1104858	
	1104922	
	1104923	
	1105068	
RC7620	1104625	
	1104693	
	1104914	
	1104915	
RC7620-1	1104626	
	1104694	
	1104762	
	1104842	
	1104894	
	1104916	
	1105067	
RC7630	1104743	
	1104812	
RC7630	1104912	
	1104924	
RC7630-1	1104742	
	1104813	

WP7603-1	1103695	Yes
	1104135	
	1104250	
	1104251	
	1104339	
	1104603	
WP7607	1103508	
	1104192	
	1104197	
	1104293	
	1104892	
WP7607-1	1104186	
	1104188	
	1104193	
	1104198	
	1104557	
	1104604	
	1104679	
	1104774	
	1104893	
WP7611	1104795	
	1104840	
	1104895	
	1104904	
WP7611-1	1104671	
	1104751	
	1104796	
	1104818	
WP7702 Octave	1104405	
	1105033	
FX30 CAT 1 EMEA	1104627	
FX30 CAT 1 NAM	1104778	
FX30S CAT 1 NAM	1104779	
FX30 CAT M1	1104896	
	1104899	
	1105031	
	1105072	
	1105074	
FX30S CAT M1	1104897	
	1104900	
	1104957	
	1105032	
	1105073	
	1105075	
GL7611	1104941	