

Product Advisory

Issue Date: March 30, 2022

Advisory Type:

9361-8i, 9311-8i, and 9300-8i Regulator Supply Update

Description:

Broadcom is proactively identifying and working to mitigate component supply constraints to ensure supply continuity of MegaRAID and HBA adapters.

As part of this, Broadcom identified the regulator supplier used on SAS3108 and SAS3008 adapter products cannot support enough regulators to meet Broadcom's demand. To mitigate shortages, DCSG is adding an alternate regulator supplier to the channel 9361-8i, 9311-8i, and 9300-8i products. The alternate regulator has been tested and verified. There are no changes to the product part numbers, but the minor revision of the SKU (shown in red) will be updated to indicate the alternate source has been applied.

Adapter Name	Type	Current Part Number	Future Part Number
LSI00417 MR SAS 9361 8I SINGLE KIT 1GB	MR	05-25420-08 D	05-25420-08 E
LSI00462 MR SAS 9361 8I 2GB C A 00	MR	05-25420-17 004	05-25420-17 005
MR SAS 9361-8I C0 2GB C D 00 FL	MR	03-25420-08 C	03-25420-08 D
S9311-8I	HBA	H5-25573-00 J	H5-25573-00 K
LSI00344 SAS9300-8I SINGLE PACK	HBA	H3-25461-02 J	H3-25461-02 K

Effective Date of Change:

Based on demand and build scheduling, customers can receive boards with either regulator starting in the May 2022 timeframe.

The changes to these Broadcom parts have been reviewed and approved by Broadcom engineers and managers per Broadcom procedure: Change Control and Customer Notification A-5962-6052-80.

Please contact your Broadcom Inc. field sales engineer or Contact Center (<http://www.broadcom.com/contact/>) for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.