

Product Obsolescence Notification

Issue Date: 18th Nov, 2020

OBS1118204D1

Dear Customer,

Broadcom regrets to announce the obsolescence of the following encoder product:

Encoder Part Number	Description
AS33-M50M-B73	33mm Mod 50b MT 7V M3 Hub Biss
AS33-M50M-S74	33mm Mod 50b MT 7V M4 Hub SSI
AS33-M50M-K53	33mm Mod 50b MT 5V M3 Hub 485
AS33-M50M-B53	33mm Mod 50b MT 5V M3 Hub Biss
AS33-M50M-K54	33mm Mod 50b MT 5V M4 Hub 485
AS33-M50M-B54	33mm Mod 50b MT 5V M4 Hub Biss
AS33-M50M-S53	33mm Mod 50b MT 5V M3 Hub SSI
AS33-M50M-K73	33mm Mod 50b MT 7V M3 Hub 485
AS33-M50M-K74	33mm Mod 50b MT 7V M4 Hub 485
AS33-M50M-S73	33mm Mod 50b MT 7V M3 Hub SSI
AS33-M50M-S54	33mm Mod 50b MT 5V M4 Hub SSI
AS33-M50M-B74	33mm Mod 50b MT 7V M4 Hub Biss

Electronic Calibration Set Part Number	Description
AS33-M50-010	AS33-M50 Elec. Calibration Set

The Key Milestones in this obsolescence process are: -

- 1. Formal customer notification beginning 01st December, 2020**
- 2. Final customer order date by 01st June, 2021**
- 3. Final ship date to customer by 01st December, 2021**

Reasons for Obsolescence

This is part of our product life cycle management program. Only the above part numbers are affected by this program as this product has approached the end of its product life cycle. Replacement Part Number

Encoder Part Number	Description
AS33-M42M-B73	33mm Mod 42b MT 7V M3 Hub Biss
AS33-M42M-S74	33mm Mod 42b MT 7V M4 Hub SSI
AS33-M42M-K53	33mm Mod 42b MT 5V M3 Hub 485
AS33-M42M-B53	33mm Mod 42b MT 5V M3 Hub Biss
AS33-M42M-K54	33mm Mod 42b MT 5V M4 Hub 485
AS33-M42M-B54	33mm Mod 42b MT 5V M4 Hub Biss
AS33-M42M-S53	33mm Mod 42b MT 5V M3 Hub SSI
AS33-M42M-K73	33mm Mod 42b MT 7V M3 Hub 485
AS33-M42M-K74	33mm Mod 42b MT 7V M4 Hub 485
AS33-M42M-S73	33mm Mod 42b MT 7V M3 Hub SSI
AS33-M42M-S54	33mm Mod 42b MT 5V M4 Hub SSI
AS33-M42M-B74	33mm Mod 42b MT 7V M4 Hub Biss

Electronic Calibration Set Part Number	Description
AS33-M42-010	AS33-M42 Elec. Calibration Set

Please note that Broadcom reserves the right to limit lifetime buy quantities based on capacity and material availability.

If you have any questions about this obsolescence, please do not hesitate to contact your local Broadcom sales representative or authorized distributors.

**Motion Control Products Division
Broadcom**

_ Please contact your Broadcom field sales engineer for any questions or support requirements.