

PRODUCT CHANGE NOTIFICATION

#PCN-MI-3W6E-16

Business Unit	Product Line Code	Type of Change	Action	Date of issue
MI	BG4	Electrical	Notify Distributors and Field	1/11/2016

The following Phoenix Contact products have been modified. Existing specifications will be met or exceeded. Please review and acknowledge this document and inform your personnel as needed.

Description of Change:

UL943 was revised to ensure safe operation and proper wiring of GFI receptacles. GFI receptacles will contain a self-test or auto-monitoring circuit that tests the ability of the GFI to detect a ground fault. If self-test detects a problem, the GFI must deny power and provide visual indication of fault. Also, the GFI must detect when the line and load are reverse-wired and deny power to the face.

The new versions will contain two separate LEDs instead of one.

Warranty Information:

Stock Status

Can existing stock still be used? Y

Is mixture of stock acceptable? N

Transaction Dates:


Date modification goes into effect from Germany: 1/1/2016

Expected first shipment (from Phoenix Contact) of the modified product(s): 1/1/2016

PRODUCT CHANGE NOTIFICATION

Current production state 3)

New production state 3)



Should you have any issues with the timeline or content of this change, please contact Phoenix Contact using the contact information below. Customers should acknowledge receipt of the PCN within 30 days of delivery of the PCN; provided, however that the failure to acknowledge receipt does not affect the product change or the effective date thereof.

PRODUCT CHANGE NOTIFICATION

Contact Info:

Larry Freeland
Senior Product Marketing Manager
(800)888-7388x3209
lfreeland@phoenixcon.com

Thank you,



Larry Freeland, Senior Product Marketing Manager

Part#	Type Description
5600639	EM-DUO 120/15/GFI/AUX
5604775	EM-DUO 120/15/GFI/V/H
5602519	EM-DUO 120/20/GFI
5603049	EM-DUO 120/20/GFI/AUX
5604777	EM-DUO 120/20/GFI/V/H
5600462	EM-DUO/120/15/GFI
5602192	EM-DUO120/20/GFI/AUX/NO