

# Product Change Notification

BECOM BLUETECHNIX PCN: PCN2018001

Publication Date: February 26, 2018

Effectivity Date: August 01, 2018

<b>Type of Change</b>	Major part change
<b>Title of Change</b>	CM-BF537 PCB and Flash change
<b>Description of Change</b>	New PCB for CM-BF537 and former RAM of CM-BF537 will be exchanged with newer version.
<b>Reason for Change</b>	Former NOR Flash IC is EOL.
<b>Action Required from Customer (Action Item #1)</b>	<p>New NOR flash is not Intel Strata compatible.</p> <p>New driver for programming the flash is needed. New driver for VDSP++ Flash Programming Tool available from BECOM BLUETECHNIX.</p> <p>Customer software for NOR flash programming, block erase or chip erase may be necessary to change.</p>

## Last time Buy/Remaining Stock

**Contact Information** Contact – BECOM BLUETECHNIX GmbH: [office@bluetechnix.com](mailto:office@bluetechnix.com)

**Product(s) Affected**

- 100-1221-3 CM-BF537-C-C-Q25S32F4 (CM-BF537E)
- 100-1229-3 CM-BF537-C-I-Q25S32F4 (CM-BF537E-I)
- 100-1272-3 CM-BF537-C-C-Q25S64F8-COSI (CM-BF537E-COSI)
- 100-1273-3 CM-BF537-C-C-Q25S64F4 (CM-BF537E-64SD)
- 100-1274-3 CM-BF537-C-I-Q25S64F8-ALST
- 100-1275-3 CM-BF537-C-I-Q25S64F8 (CM-BF537E-I-64SD)

**Support Link** [https://support.bluetechnix.at/wiki/Revision\\_Report\\_CM-BF537E](https://support.bluetechnix.at/wiki/Revision_Report_CM-BF537E)

---

## Detailed Information

100-1221-3 CM-BF537-C-C-Q25S32F4 (CM-BF537E)

Part	V3.3.x	V3.4.y	Customer Action
Flash	PF48F3000P0ZBQEA	S29GL256S90GHI020	See (action item #1)
PCB	V3.3	V3.4	See (action item #1)

Lack of acknowledgement / concern response of the PCN within 20 days constitutes acceptance of the change.



**100-1229-3** CM-BF537-C-I-Q25S32F4 (CM-BF537E-I)

Part	V3.3.x	V3.4.y	Customer Action
Flash	PF48F3000P0ZBQEA	S29GL256S90GHI020	See (action item #1)
PCB	V3.3	V3.4	See (action item #1)

**100-1272-3** CM-BF537-C-C-Q25S64F8-COSI (CM-BF537E-COSI)

Part	V3.3.x	V3.4.y	Customer Action
Flash	PF48F3000P0ZBQEA	S29GL256S90GHI020	See (action item #1)
PCB	V3.3	V3.4	See (action item #1)

**100-1273-3** CM-BF537-C-C-Q25S64F4 (CM-BF537E-64SD)

Part	V3.3.x	V3.4.y	Customer Action
Flash	PF48F3000P0ZBQEA	S29GL256S90GHI020	See (action item #1)
PCB	V3.3	V3.4	See (action item #1)

**100-1274-3** CM-BF537-C-I-Q25S64F8-ALST

Part	V3.3.x	V3.4.y	Customer Action
Flash	PF48F3000P0ZBQEA	S29GL256S90GHI020	See (action item #1)
PCB	V3.3	V3.4	See (action item #1)

**100-1275-3** CM-BF537-C-I-Q25S64F8 (CM-BF537E-I-64SD)

Part	V3.3.x	V3.4.y	Customer Action
Flash	PF48F3000P0ZBQEA	S29GL256S90GHI020	See (action item #1)
PCB	V3.3	V3.4	See (action item #1)

Should you have any further queries, please do not hesitate to contact our support team which will be happy to help furnish you any other information that you require.

Lack of acknowledgement / concern response of the PCN within 20 days constitutes acceptance of the change.