

PRODUCT CHANGE NOTIFICATION

Product Category COPPER PATCHCORDS 20230920-1

Product Group ENTERPRISE CONNECTIVITY

ISSUE DATE: 20-Sep-23

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Select harnesses and plug packs are being discontinued due to shifts in market demand. Please use equivalent patch cord replacement

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2023	12	19

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CSVM@panduit.com	CHINA: 400-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com	
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) SGP-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com	
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com	
	TAIWAN: 0080 165 1487 SGP-Customer_Service@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com		
	LATIN AMERICA	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customerService@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA FORM C2-1003 DATE: 06 APR 21 APPR. MURILLO	EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com	

IMPACTED PART NUMBER(s)	Replacement Part 1	Discontinuation Date
QPPLD6-X	NO-REPLACEMENT	19-DEC-2023
QPPLD8-X	NO-REPLACEMENT	19-DEC-2023
QPPN8BL	NO-REPLACEMENT	19-DEC-2023
QPPN8RD	NO-REPLACEMENT	19-DEC-2023
QPPNS6BU	QPPNS6BL	19-DEC-2023
QPPNS6WH	QPPNS6BL	19-DEC-2023
QPPNSTRP6BL	NO-REPLACEMENT	19-DEC-2023
QCCUDB6BB09N	NO-REPLACEMENT	19-DEC-2023
QCCUDB6BB13N	NO-REPLACEMENT	19-DEC-2023
QCCUDB6BB15N	NO-REPLACEMENT	19-DEC-2023
QCCUDB6BB18N	NO-REPLACEMENT	19-DEC-2023
QCCUDB6BB22N	NO-REPLACEMENT	19-DEC-2023
QCCUDB6BB25N	NO-REPLACEMENT	19-DEC-2023
QCCUDB6BB31N	NO-REPLACEMENT	19-DEC-2023
QPPSDBML10N	NO-REPLACEMENT	19-DEC-2023
QPPSDRML10N	NO-REPLACEMENT	19-DEC-2023
QPCSDNLLB10N	NO-REPLACEMENT	19-DEC-2023
QPCSD6XB05	NO-REPLACEMENT	19-DEC-2023
QPCSD6XB08N	NO-REPLACEMENT	19-DEC-2023
QPCSD6XB10	NO-REPLACEMENT	19-DEC-2023
QPCSD6XB20	NO-REPLACEMENT	19-DEC-2023
QPCSD6XG10N	NO-REPLACEMENT	19-DEC-2023
QPCSD6XL08N	NO-REPLACEMENT	19-DEC-2023
QPCSD6XO08N	NO-REPLACEMENT	19-DEC-2023
QPCSD6XR08N	NO-REPLACEMENT	19-DEC-2023
QPCSD6XR10N	NO-REPLACEMENT	19-DEC-2023
QPCSD6XV10N	NO-REPLACEMENT	19-DEC-2023
QPCSD6XW10N	NO-REPLACEMENT	19-DEC-2023
QPCSD6XY08N	NO-REPLACEMENT	19-DEC-2023
QPCSDBRB05	NO-REPLACEMENT	19-DEC-2023
QPCSDBRB10	NO-REPLACEMENT	19-DEC-2023
QPCSDBRB14	NO-REPLACEMENT	19-DEC-2023
QPCSDWBXB05	NO-REPLACEMENT	19-DEC-2023
QPCSDWBXB10	NO-REPLACEMENT	19-DEC-2023
QPCSDWBXB14	NO-REPLACEMENT	19-DEC-2023
QPCSDWBXB3MN	NO-REPLACEMENT	19-DEC-2023
QPCSDW6XL2M	NO-REPLACEMENT	19-DEC-2023
QPCSDW6XL3M	NO-REPLACEMENT	19-DEC-2023
QPCSDW6XL5M	NO-REPLACEMENT	19-DEC-2023
QPCSDWRSL2M	NO-REPLACEMENT	19-DEC-2023
QPCSDWRSL3M	NO-REPLACEMENT	19-DEC-2023
QPCSDWRSL5M	NO-REPLACEMENT	19-DEC-2023
QPCSDWRSL7MN	NO-REPLACEMENT	19-DEC-2023
QPCSDWRSL9MN	NO-REPLACEMENT	19-DEC-2023
QPCSDWWXL2M	NO-REPLACEMENT	19-DEC-2023

QPCSDWXXL4M	NO-REPLACEMENT	19-DEC-2023
QPCSDWXXL6M	NO-REPLACEMENT	19-DEC-2023
QPCUDB6XB05	NO-REPLACEMENT	19-DEC-2023
QPCUDB6XB10	NO-REPLACEMENT	19-DEC-2023
QPCUDB6XB20	NO-REPLACEMENT	19-DEC-2023
QPCUDBR5B05	NO-REPLACEMENT	19-DEC-2023
QPCUDBR5B10	NO-REPLACEMENT	19-DEC-2023
QPCUDBR5B20	NO-REPLACEMENT	19-DEC-2023
QPCUDBWXB05	NO-REPLACEMENT	19-DEC-2023
QPCUDBWXB10	NO-REPLACEMENT	19-DEC-2023
QPCUDBWXB20	NO-REPLACEMENT	19-DEC-2023
QPCUDW6XL2M	NO-REPLACEMENT	19-DEC-2023
QPCUDW6XL3M	NO-REPLACEMENT	19-DEC-2023
QPCUDW6XL4M	NO-REPLACEMENT	19-DEC-2023
QPCUDW6XL5M	NO-REPLACEMENT	19-DEC-2023
QPCUDW6XL6M	NO-REPLACEMENT	19-DEC-2023
QPCUDWR5L2M	NO-REPLACEMENT	19-DEC-2023
QPCUDWR5L3M	NO-REPLACEMENT	19-DEC-2023
QPCUDWR5L4M	NO-REPLACEMENT	19-DEC-2023
QPCUDWR5L5M	NO-REPLACEMENT	19-DEC-2023
QPCUDWR5L6M	NO-REPLACEMENT	19-DEC-2023
QPCUDWXXL2M	NO-REPLACEMENT	19-DEC-2023
QPCUDWXXL3M	NO-REPLACEMENT	19-DEC-2023
QPCUDWXXL4M	NO-REPLACEMENT	19-DEC-2023
QPCUDWXXL5M	NO-REPLACEMENT	19-DEC-2023
QPCVDB55L6MN	NO-REPLACEMENT	19-DEC-2023
QPCVDG6XL14MN	NO-REPLACEMENT	19-DEC-2023
QPCVDW6XL3M	NO-REPLACEMENT	19-DEC-2023
QPCVDW6XL5M	NO-REPLACEMENT	19-DEC-2023
QPCVDW6XL6M	NO-REPLACEMENT	19-DEC-2023
QPCVDWR5L2M	NO-REPLACEMENT	19-DEC-2023
QPCVDWR5L4M	NO-REPLACEMENT	19-DEC-2023
QPCVDWR5L5M	NO-REPLACEMENT	19-DEC-2023
QPCVDWR5L6M	NO-REPLACEMENT	19-DEC-2023
QPCVDWXXL2M	NO-REPLACEMENT	19-DEC-2023
QPCVDWXXL3M	NO-REPLACEMENT	19-DEC-2023
QPCVDWXXL4M	NO-REPLACEMENT	19-DEC-2023
QPCVDWXXL5M	NO-REPLACEMENT	19-DEC-2023
QPCVDWXXL6M	NO-REPLACEMENT	19-DEC-2023
QCFS2LOL2Y10N	NO-REPLACEMENT	19-DEC-2023
QPJUDB6XB06N	NO-REPLACEMENT	19-DEC-2023
QPJUDB6XB07N	NO-REPLACEMENT	19-DEC-2023
QPJUDB6XB08N	NO-REPLACEMENT	19-DEC-2023
QPJUDB6XB10N	NO-REPLACEMENT	19-DEC-2023
QPJUDB6XB12N	NO-REPLACEMENT	19-DEC-2023
QPJUDB6XB14N	NO-REPLACEMENT	19-DEC-2023
QPJUDB6XB16N	NO-REPLACEMENT	19-DEC-2023
QPJUDB6XB20N	NO-REPLACEMENT	19-DEC-2023

QPJUDB6XB22N	NO-REPLACEMENT	19-DEC-2023
QPJUDW6XR06N	NO-REPLACEMENT	19-DEC-2023
QPJUDW6XR08N	NO-REPLACEMENT	19-DEC-2023
QPPSDBDB03	NO-REPLACEMENT	19-DEC-2023
QPPSDBDB05	NO-REPLACEMENT	19-DEC-2023
QPPSDBDB10	NO-REPLACEMENT	19-DEC-2023
QPPSDBNL10N	NO-REPLACEMENT	19-DEC-2023
QPPSDBRS03	NO-REPLACEMENT	19-DEC-2023
QPPSDBRS07	NO-REPLACEMENT	19-DEC-2023
QPPSDBRS14	NO-REPLACEMENT	19-DEC-2023
QPPSDWDL1M	NO-REPLACEMENT	19-DEC-2023
QPPSDWDL3M	NO-REPLACEMENT	19-DEC-2023
QPPSDWDL5M	NO-REPLACEMENT	19-DEC-2023
QPPSDWRS1M	NO-REPLACEMENT	19-DEC-2023
QPPSDWRS3M	NO-REPLACEMENT	19-DEC-2023
QPPSDWRS5M	NO-REPLACEMENT	19-DEC-2023
QPPUDWHL2MN	NO-REPLACEMENT	19-DEC-2023
QPPUDWRS1M	NO-REPLACEMENT	19-DEC-2023
QPPUDWRS3M	NO-REPLACEMENT	19-DEC-2023
QPPUDWRS5M	NO-REPLACEMENT	19-DEC-2023
QPPVDWRS1M	NO-REPLACEMENT	19-DEC-2023
QPPVDWRS3M	NO-REPLACEMENT	19-DEC-2023
QPPVDWRS5M	NO-REPLACEMENT	19-DEC-2023
QPPN8BU	NO-REPLACEMENT	19-DEC-2023
QPPN8WH	NO-REPLACEMENT	19-DEC-2023
QPPNS6RD	QPPNS6BL	19-DEC-2023
QPPNR6S	NO-REPLACEMENT	19-DEC-2023
QCCUDB6BB12N	NO-REPLACEMENT	19-DEC-2023
QCCUDB6BB16N	NO-REPLACEMENT	19-DEC-2023
QCCUDB6BB19N	NO-REPLACEMENT	19-DEC-2023
QCCUDB6BB28N	NO-REPLACEMENT	19-DEC-2023
QCCUDB6BB34N	NO-REPLACEMENT	19-DEC-2023
QPCSDNLLB07N	NO-REPLACEMENT	19-DEC-2023
QPCSDNWXB14N	NO-REPLACEMENT	19-DEC-2023
QPCSDB6XB07	NO-REPLACEMENT	19-DEC-2023
QPCSDB6XB14	NO-REPLACEMENT	19-DEC-2023
QPCSDB6XG08N	NO-REPLACEMENT	19-DEC-2023
QPCSDB6XL10N	NO-REPLACEMENT	19-DEC-2023
QPCSDB6XO10N	NO-REPLACEMENT	19-DEC-2023
QPCSDB6XV08N	NO-REPLACEMENT	19-DEC-2023
QPCSDB6XW08N	NO-REPLACEMENT	19-DEC-2023
QPCSDB6XY10N	NO-REPLACEMENT	19-DEC-2023
QPCSDBRSB07	NO-REPLACEMENT	19-DEC-2023
QPCSDBRSB20	NO-REPLACEMENT	19-DEC-2023
QPCSDBWXB07	NO-REPLACEMENT	19-DEC-2023
QPCSDBWXB20	NO-REPLACEMENT	19-DEC-2023
QPCSDN6XG10N	NO-REPLACEMENT	19-DEC-2023
QPCSDW6XL4M	NO-REPLACEMENT	19-DEC-2023

QPCSDW6XL6M	NO-REPLACEMENT	19-DEC-2023
QPCSDWRS14M	NO-REPLACEMENT	19-DEC-2023
QPCSDWRS16M	NO-REPLACEMENT	19-DEC-2023
QPCSDWRS18MN	NO-REPLACEMENT	19-DEC-2023
QPCSDWWSL3M	NO-REPLACEMENT	19-DEC-2023
QPCSDWWSL5M	NO-REPLACEMENT	19-DEC-2023
QPCUDB6XB07	NO-REPLACEMENT	19-DEC-2023
QPCUDB6XB14	NO-REPLACEMENT	19-DEC-2023
QPCUDBRSB07	NO-REPLACEMENT	19-DEC-2023
QPCUDBRSB14	NO-REPLACEMENT	19-DEC-2023
QPCUDBWXB07	NO-REPLACEMENT	19-DEC-2023
QPCUDBWXB14	NO-REPLACEMENT	19-DEC-2023
QPCUDWWSL6M	NO-REPLACEMENT	19-DEC-2023
QPCVDW6XL2M	NO-REPLACEMENT	19-DEC-2023
QPCVDW6XL4M	NO-REPLACEMENT	19-DEC-2023
QPCVDWBLL5M	NO-REPLACEMENT	19-DEC-2023
QPCVDWRS13M	NO-REPLACEMENT	19-DEC-2023
QPJUDW6XR07N	NO-REPLACEMENT	19-DEC-2023
QPJUDW6XR10N	NO-REPLACEMENT	19-DEC-2023
QPPSDBDB07	NO-REPLACEMENT	19-DEC-2023
QPPSDBDB14	NO-REPLACEMENT	19-DEC-2023
QPPSDBRS05	NO-REPLACEMENT	19-DEC-2023
QPPSDBRS10	NO-REPLACEMENT	19-DEC-2023
QPPSDWDL2M	NO-REPLACEMENT	19-DEC-2023
QPPSDWDL4M	NO-REPLACEMENT	19-DEC-2023
QPPSDWRS2M	NO-REPLACEMENT	19-DEC-2023
QPPSDWRS4M	NO-REPLACEMENT	19-DEC-2023
QPPUDWHL1MN	NO-REPLACEMENT	19-DEC-2023
QPPUDWRS2M	NO-REPLACEMENT	19-DEC-2023
QPPUDWRS4M	NO-REPLACEMENT	19-DEC-2023
QPPVDWRS2M	NO-REPLACEMENT	19-DEC-2023
QPPVDWRS4M	NO-REPLACEMENT	19-DEC-2023