



# Product Change Notice

PCN Number: 13-1146-02-02  
Issue Date: 04-DECEMBER-2014

**Exar Corporation**

[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

**PRODUCTS AFFECTED:**

SPX5205M5-L	SPX5205M5-L/TR
SPX5205M5-L-3-3	SPX5205M5-L-3-3/TR
SPX5205M5-L-5-0	SPX5205M5-L-5-0/TR

**CHANGE CATEGORY:**

- |  |                                    |  |
|--|------------------------------------|--|
| <input type="checkbox"/> Material                                  | <input type="checkbox"/> Process   | <input type="checkbox"/> Package                     |
| <input type="checkbox"/> Design                                    | <input type="checkbox"/> Datasheet | <input checked="" type="checkbox"/> Packing/Shipping |
| <input checked="" type="checkbox"/> Other: Alternate Assembly Site |                                    |  |

**DESCRIPTION OF CHANGE:**

1. Addition of an alternate qualified location, JCET, for assembly using copper wire or gold wire bonding.
2. Standard reel quantity will change from 2500 pieces to 3000 pieces.

**IMPACT OF CHANGE:**

There is no change to product form, fit or function.

**TARGET IMPLEMENTATION DATE:** 04-MARCH-2015

Please contact customer support ([customersupport@exar.com](mailto:customersupport@exar.com)) for sample date availability or qualification data

**PROPRIETARY INFORMATION**

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.