

While OmniOn Power continues to hold to its position that its PCN obligations are solely to those customers who purchase product directly from OmniOn Power, OmniOn Power commits to working with its direct customers to improve the process of notifying end customers. To support this commitment, OmniOn Power customers and their suppliers should provide PCN contact information and any updates to that information to OmniOn Power by sending an email to the following email alias: DL-ELPC-!US_EL_ELIS_pcn.product.change.notice@omnionpower.com.

The actual product change notice is as follows...

OmniOn Power
CUSTOMER TECHNICAL SUPPORT CENTER
PRODUCT CHANGE NOTIFICATION

Notification No: cn119937 Date: 2-29-2024

Change Information

For Notification Only

Product Change Class: D

Description of Change:

|New powder coating will be added as second source. Color will be green instead of blue. No change in fit and function.

Estimated Implementation Date: 2024-02-29

Material Affected

Operation	Old Comcode	Old Part Number	New Comcode	New Part Number	New Qty	New Assy	BD	Ref
-----------	-------------	-----------------	-------------	-----------------	---------	----------	----	-----

Products Affected

Product Type:

Affected Product:

- 150021954 EBVW025A0B9641-HZ
- 150032026X XQSDW035A0B41-HZ
- 150023769 EBDW020A0B641-HZ
- 1600282074A QSVW042A0B641-36LHZ
- 150048763 EBVW020A0B841-HZ
- 150044040X XQSDW042A0B641-HZ
- 150032946 QSDK060A0B41-HZ
- 150048362 QSVW035A0B41-PHZ
- 1600178937A QBVE067A0B41-02XHZ
- 150046500 QSDW020A0A941-46HZ
- 1600311051A EBVW025A0B941-HZ
- 1600177237A QBVE067A0B41-02HZ

150051687 QBDE055A0B641-PHZ
1600450138A XQSDW050A0B641-PHZ
1600408149A QBDE067A0B641-53HZ
1600408150A QBDE067A0B641-53PHZ
150039184 QSVW035A0B641-HZ
150051688 QBDE055A0B641-HZ
1600210157AX XEBDW025A0B41-77HSZ
150047226 QBVE067A0B841-HZ
1600244917A EBDW025A0B841-HZ
1600141337A EBDW025A0B41-HSZ
150037988 QSVW050A0B41-HZ
150044443 QSVW050A0B41-PHZ
150032176 QSVW035A0B41-HZ
150044040 QSDW042A0B641-HZ
1600459372A EBVW033A0B941-HZ
CC109167516 EBVW020A0B41-HZ
1600096714A QBDE067A0B641-02PHZ
1600483269A QBDE067A0S8R541-48HZ
1600115461A QSDW042A0B841-PHZ
1600372563A QBVE067A0B641-02HZ
150020433 EBVW020A0B641-HZ
150048509 QBVE067A0B641-HZ
1600338617A QBDE067A0S8R541-47HZ
150039184X XQSVW035A0B641-HZ
150021954X XEBVW025A0B9641-HZ
150039419 QSVW042A0B41-HZ
1600096707A QSVW035A0B41-88PHZ
150046160 EBVW020A0B941-HZ
1600171477A QBVE067A0B41-77PHZ
150044272 QSDW042A0B641-PHZ
150048323X XQSVW042A0B41-62LHZ_
150030861 EBVW025A0B9641-PHZ
1600299257A EBDW025A0B641-DHZ
1600210157A EBDW025A0B41-77HSZ
1600242717A QBDE067A0B641HF-PHZ
1600338637A QBDE067A0S8R541-47HZ_
1600233937A QBDE055A0B641-02PHZ
150044444 QBVE067A0B41-PHZ
150023485 EBVW025A0B41-HZ
150051263 QSDW035A0B641-PHZ
150044446X XQSDW050A0B41-PHZ
1600108118A QSVW035A0B41-28HZ
CC109167490 EBDW020A0B41-HZ
150023769X XEBDW020A0B641-HZ
150044013 QSVW035A0S14R041-46HZ
150048763X XEBVW020A0B841-HZ
1600372132A QSVW050A0B941-PHZ
1600399014A EBVW020A0B641-02HZ

1600324717A EBDW020A0B641-022HZ
150037986 QSDW050A0B41-HZ
150040687 QBVE067A0B41-HZ
1600086585A EBVW025A0B641-PHZ
1600334137A EBVW025A0B41-21HZ
1600144177A EBDW025A0B41-76HSZ
150044446 QSDW050A0B41-PHZ
150023453 EBDW025A0B641-HZ
CC109170552 EBDW020A0B641-PHZ
150043604 QBVE050A0B81-76HZ
1600437559A QSVW050A0B41-28PHZ
150048323 QSVW042A0B41-62LHZ
150051687X XQBDE055A0B641-PHZ
150048506 QSDW050A0B641-PHZ
1600274658A QSDW042A0B41-58HZ
1600091245AX XQSDW035A0B641-62PHZ
150023453X XEBDW025A0B641-HZ
150040687X XQBVE067A0B41-HZ_
150042403 QSDW042A0B41-HZ
1600447332A QSDW035A0B641-54HZ
CC109172334 EBVW020A0B41-PHZ
1600471058A QBVE067A0B841-PHZ
150048677 QSVW042A0B9641-HZ
150049071 QBDE067A0B641-PHZ
1600178939A QBDE067A0B641-02XPHZ_
150052496 QSVW050A0B641-HZ
CC109172945 EBDW025A0B641-PHZ
150032026 QSDW035A0B41-HZ
150033148 EBDW025A0B641-03HZ
150050374 QBDE067A0B41-HZ
150042781 QSVW042A0B641-HZ
150037378 QSVW035A0B61-HZ
CC109172318 EBVW020A0B9641-HZ
150046499 QSDW007A5C941-46HZ
150051688X XQBDE055A0B641-HZ
150021143 EBVW020A0B64-HZ
1600178938A QBDE055A0B641-XPHZ
150035275 EBDW020A0B841-02HZ
150029296 EBVW025A0B641-HZ
150029356 EBDW020A0B841-HZ
1600091245A QSDW035A0B641-62PHZ
150050860 QBDE067A0B641-HZ
1600253758A QSVW042A0B941-HZ
150027293 EBDW020A0B641-02HZ
1600480559A QSDW050A0B41-21PHZ
150052899 QSDG020A0U41-76HZ

Further information regarding this change can be obtained from:

OmniOn Power
Customer Technical Support Group
601 Shiloh Rd
Plano, TX 75074 (USA)
972-244-9288

Attn: Franz Martin franz.martin@omnionpower.com
DL-ELPC-IUS_EL_ELIS_pcn.product.change.notice@omnionpower.com