



CUSTOMER ADVISORY

Passive x1 Fmax Spec Change for Trion® T120, T85 and T55 FPGAs

| | |
|--------------------------------|---|
| <p>Advisory Details</p> | <p>Passive mode X1 configuration clock frequency ($f_{MAX,S}$) has been changed for optimum performance:</p> <ul style="list-style-type: none"> • C4L and I4L Parts: Reduced to 10MHz maximum. • C3, C4 and I4 Parts: Reduced to 12.5MHz maximum. <p>Customers can refer to the following collaterals for details:</p> <ul style="list-style-type: none"> • T120 Data Sheet • T85 Data Sheet • T55 Data Sheet |
| <p>Parts Affected</p> | <p>Trion® FPGAs shown below:</p> <ul style="list-style-type: none"> • T55/T85/T120F324XX • T55/T85/T120F484XX • T55/T85/T120F576XX <p>XX = All speed grades</p> |
| <p>Contact:</p> | <p>For more information, please contact your local Sales or FAE or contact us online at https://www.efinixinc.com/company-contact-us.html.</p> |