

PRODUCT CHANGE NOTIFICATION

Product Category INDUSTRIAL NETWORKS SOFTWARE & SERVICES **20200610-01**

Product Group INDUSTRIAL NETWORKS SOFTWARE & SERVICES

ISSUE DATE: 20200617

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Industrial Networks wireless sensors and software are being discontinued in order to streamline the Industrial Network product offering. This product will be discontinued globally.

Please review Product Change Notification for further information.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2020	9	31

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s 1/1/19 Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Type
IOT-2SW250M	No Replacement
IOT-2SW2K	No Replacement
IOT-2SW2KM	No Replacement
IOT-9CHT	No Replacement
IOT-9CHT-2	No Replacement
IOT-9CHT-4	No Replacement
IOT-9CHT-8	No Replacement
IOT-9CLT	No Replacement
IOT-9CLT-2	No Replacement
IOT-9CLT-4	No Replacement
IOT-9CLT-8	No Replacement
IOT-9CLTL17	No Replacement
IOT-9CLTL17-2	No Replacement
IOT-9CLTL17-4	No Replacement
IOT-9CLTL17-8	No Replacement
IOT-9CLTL34	No Replacement
IOT-9CLTL34-2	No Replacement
IOT-9CLTL34-4	No Replacement
IOT-9CLTL34-8	No Replacement
IOT-9CLTL-4	No Replacement
IOT-9CM150	No Replacement
IOT-9CM150-2	No Replacement
IOT-9CM150-4	No Replacement
IOT-9CM150-8	No Replacement
IOT-9CM20	No Replacement
IOT-9CM20-2	No Replacement
IOT-9CM20-4	No Replacement
IOT-9CM20-8	No Replacement
IOT-9CM20M	No Replacement
IOT-9CM20M-2	No Replacement
IOT-9CM20M-4	No Replacement
IOT-9CSW100	No Replacement
IOT-9CSW25	No Replacement
IOT-9CSW50	No Replacement
IOT-9CSW500	No Replacement
IOT-9CSW6	No Replacement
IOT-9CSW999	No Replacement
IOT-9CT-4	No Replacement
IOT-9CTHL03	No Replacement
IOT-9CTHL03-2	No Replacement
IOT-9CTHL03-4	No Replacement
IOT-9CTHL03-8	No Replacement
IOT-9CTHL03-X	No Replacement
IOT-9CTL03-4	No Replacement
IOT-9CTL03-X	No Replacement
IOT-9CT-X	No Replacement

IOT-9CVM-4	No Replacement
IOT-9CVM-X	No Replacement
IOT-9DC	No Replacement
IOT-9DC-2	No Replacement
IOT-9DC-4	No Replacement
IOT-9DC-8	No Replacement
IOT-9EMON	No Replacement
IOT-9EMON-2	No Replacement
IOT-9EMON-4	No Replacement
IOT-9EMON-8	No Replacement
IOT-9GWPOE-4	No Replacement
IOT-9IP65GWE	No Replacement
IOT-9IP65SE	No Replacement
IOT-9OC	No Replacement
IOT-9OC-2	No Replacement
IOT-9OC-4	No Replacement
IOT-9OC-8	No Replacement
IOT-9OC-X	No Replacement
IOT-9PB	No Replacement
IOT-9PB-2	No Replacement
IOT-9PB-4	No Replacement
IOT-9PB-8	No Replacement
IOT-9PC01	No Replacement
IOT-9PC01-2	No Replacement
IOT-9PC01-4	No Replacement
IOT-9PC01-8	No Replacement
IOT-9PC04	No Replacement
IOT-9PC04-2	No Replacement
IOT-9PC04-4	No Replacement
IOT-9PC04-8	No Replacement
IOT-9PS300	No Replacement
IOT-9PS300-2	No Replacement
IOT-9PS300-4	No Replacement
IOT-9PS300-8	No Replacement
IOT-9SMT	No Replacement
IOT-9SMTA	No Replacement
IOT-9SW2K	No Replacement
IOT-9SW2KM	No Replacement
IOT-9SW50	No Replacement
IOT-9SW50S	No Replacement
IOT-9VM5	No Replacement
IOT-9VM5-2	No Replacement
IOT-9VM5-4	No Replacement
IOT-9VM5-8	No Replacement
IOT-9WD	No Replacement
IOT-9WD-2	No Replacement
IOT-9WD-4	No Replacement

IOT-9WD-8	No Replacement
IOT-A1DEMO	No Replacement
IOT-A1EXPD	No Replacement
IOT-A1GMT	No Replacement
IOT-A1STRT	No Replacement
IOT-A2DEMO	No Replacement
IOT-A2ENV	No Replacement
IOT-A2GEM	No Replacement