



# Product Change Notice

PCN Number: 17-0208-03  
 Issue Date: 10-MAY-2017

Exar Corporation

[www.exar.com](http://www.exar.com) | Support: customersupport@exar.com

**PRODUCTS AFFECTED:**

CLC4007ITP14MTR	SP3232EUEY-L/TR	SP3222EBCY-L/TR	SP330EEY-L
CLC4007ITP14X	SP3221EEY-L/TR	SP3222EBCY-L	XR20M1172IG28TR-F
CLC4011ITP14	SP3220EBCY-L/TR	SP3222EBEY-L/TR	XR20M1172IG28-F
CLC4011ITP14MTR	SP3220ECY-L/TR	SP3222EBEY-L	XRT85L61IG-F
CLC4011ITP14X	SP3232EEY-L	SP3222ECY-L/TR	SP3243EUEY-L/TR
SP6128AEY-L/TR	SP3220EBCY-L	SP3222ECY-L	SP3243ECY-L/TR
SP6128AEY-L	SP3220EUEY-L/TR	SP3222EEY-L/TR	SP336EEY-L/TR
SP6128AHY-L/TR	SP3232EUCY-L	SP3222EEY-L	SP3243EBEY-L/TR
XR8054ATP14	SP3220EBEY-L	SP3222EUCY-L/TR	SP3238EEY-L/TR
XR8054ATP14MTR	SP3220ECY-L	SP3222EUCY-L	SP3243EUCY-L/TR
XR8054ATP14X	SP3232EUCY-L/TR	SP3222EUEY-L/TR	SP3243EBCY-L/TR
XRA1200PIG16TR-F	SP3220EEY-L	SP3222EUEY-L	SP336EEY-L
XRA1200IG16TR-F	SP3221ECY-L/TR	SP3223EBCY-L/TR	SP3243EEY-L/TR
XRA1402IG16TR-F	SP3221ECY-L	SP3223EBEY-L/TR	SP3238EEY-L
XRA1404IG16-F	SP3221EEY-L	SP3223ECY-L/TR	SP337EBEY-L/TR
XR20M1170IG16TR-F	SP3232EBCY-L	SP3223ECY-L	SP3243EBEY-L
XR20M1170IG16-F	SP3232ECY-L	XRA1201PIG24TR-F	SP3243EUEY-L
XRA1402IG16-F	SP3232EHCY-L/TR	XRA1403IG24TR-F	SP337EUEY-L
SP3226EEY-L/TR	SP3232EHCY-L	XRA1203IG24TR-F	SP337EBEY-L
SP3227EEY-L/TR	SP3232EHEY-L/TR	XRA1201PIG24-F	SP3238ECY-L/TR
XRA1200IG16-F	SP3203EEY-L/TR	XRA1403IG24-F	SP3243EEY-L
XRA1200PIG16-F	SP3203ECY-L/TR	SP3249EEY-L/TR	SP336ECY-L
XRA1202IG16-F	SP3203EEY-L	SP3249EEY-L	SP3243EBCY-L
XRA1202IG16TR-F	XRT91L33AIG-F	XR20M1170IG24-F	SP3243EUCY-L
XRA1206IG16-F	XRT91L33AIGTR-F	XR20M1170IG24TR-F	SP3244ECY-L/TR
XRA1206IG16TR-F	XRT91L33IGTR-F	XRA1201IG24-F	SP3244ECY-L
XRA1404IG16TR-F	SP3223EEY-L/TR	XRA1201IG24TR-F	SP336ECY-L/TR
SP3232EEY-L/TR	SP3223EEY-L	XRA1203IG24-F	SP337EBCY-L/TR
SP3232ECY-L/TR	SP3223EUCY-L/TR	XRA1207IG24-F	SP337EBCY-L
SP3232EBEY-L/TR	SP3223EUCY-L	XRA1207IG24TR-F	SP337EUCY-L/TR
SP3220EBEY-L/TR	SP3223EUEY-L/TR	XRA1405IG24-F	SP337EUCY-L
SP3232EBCY-L/TR	SP3224EEY-L/TR	XRA1405IG24TR-F	SP337EUEY-L/TR
SP3220EEY-L/TR	SP3225EEY-L/TR	SP330EEY-L/TR	

**CHANGE CATEGORY:**

**PROPRIETARY INFORMATION**

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.



# Product Change Notice

PCN Number: 17-0208-03  
Issue Date: 10-MAY-2017

Exar Corporation

[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

Material

Process

Package

Design

Datasheet

Packing/Shipping

Other: Alternate Site

## DESCRIPTION OF CHANGE:

Qualification of alternate assembly subcon, JCET.

## IMPACT OF CHANGE:

There is no change to product form, fit or function.

**TARGET IMPLEMENTATION DATE:** 10-AUGUST-2017

Please contact customer support ([customersupport@exar.com](mailto:customersupport@exar.com)) for sample date availability or qualification data

### PROPRIETARY INFORMATION

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.