



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000939I

DATE: 24-Apr-2018

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Lead-Free Conversion	VT1316MAFQ-001	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Lead-Free Conversion	VT1316MAFQ-061	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Lead-Free Conversion	VT1316MAFQX-001	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Lead-Free Conversion	VT1316MAFQX-061	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	5962-9312101MPA	N/A	24-Apr-2018	24-Apr-2018	Part is leaded. Request information on lead-free version
Discontinuance	73S8004R-IL/F	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	73S8004R-ILR/F	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	73S8024R-IL/F	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	73S8024R-ILR/F	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	73S8024R-ILR/F2	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	ADC0820CC/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	DG405C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	DG441C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	DG442DK	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1086LU-834+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1089LU-C29+	DS1089LU-A29+	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1091LUB-008+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1099U-TJ+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1099U-TJ+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1706REPA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1706SEPA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1815-5+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1815R-5+T&R	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1817R-5+T&R	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1834U+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1855E-C01+T&R	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-May-2018

Discontinuance	DS1859E-015+	DS1859B-020+T&R	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1859E-015+T&R	DS1859B-020+T&R	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	DS2438Z-S+T&R	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	DS2483AQ+U	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	DS2502R+00B	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	DS2502R-00C+T&R	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	DS28CN01U-W0D+1T-C	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	DS28EL14Q-742+2T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	DS4300P+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	DS5003-CS1+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	DSRB3X-524+2T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	ENG24033EMY+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	HFRD30.1EVKIT	N/A	24-Apr-2018	24-Apr-2018	EVKIT is No Longer Supported
Discontinuance	ICL7106C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	ICL7116C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	ICL7117C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	ICL7126C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	ICL7126CQH+D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	ICL7611DC/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	ICL7612BC/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	ICM7211AI/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	ICM7212AI/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	ICM7218AI/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	ICM7218BI/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	ICM7224I/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	ICM7556I/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	IH5042C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	IH5043C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	IH5141C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	IH5341CWE+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	IH5352C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX1165ACUI+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX1177BCUP+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX1177BCUP+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX1177CCUP+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX1177CEUP+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-May-2018

Discontinuance	MAX1178CEUP+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX1179AEUI+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX1179CCUI+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX1207ETL+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX120C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX121C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX122BC/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX1284AESA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX12900ATJ+	MAX12900AATJ+	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX1367ECM+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX1367ECM+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX1367ECM+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX14512EVKIT+	MAX14526EEVKIT+	24-Apr-2018	24-Apr-2018	EVKIT is No Longer Supported
Discontinuance	MAX14512EWP+T	MAX14526EEWP+T	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX14578AEWC+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX14578EWC+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX1483C/D+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX15000BEUB+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX15005AAUA/V+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX15006CASA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX15006CASA+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX15008ATJ+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX15026BATD+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX15029AGA/VS+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX15029AGA/VS+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX1583ZETB+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX1583ZETB+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16006DTG+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16021LTEV+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16023LTAY18+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16024PTBT18+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16033LLB46+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16033PLB23+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16033PLB23+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16034LLB29+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16034LLB29+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-May-2018

Discontinuance	MAX16034LLB31+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16034LLB31+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16034LLB44+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16034PLB26+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16034PLB26+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16034PLB44+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16035LLB29+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16035LLB46+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16035LLB46+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16035PLB46+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16036PLB26+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16036PLB31+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16036PLB46+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16036PLB46+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16038LLA23+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16038PLA29+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16039PLA26+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16039PLA26+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16040LLA29+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16040LLA31+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16040LLA31+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16040PLA23+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16040PLA23+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16040PLA29+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16040PLA29+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16040PLA46+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16040PLA46+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16057ATT33+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16058ATA19+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16058ATA21+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16058ATA21+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16058ATT29+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16058ATT29+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16058ATT46+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16058ATT46+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16062CTG+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-May-2018

Discontinuance	MAX16062CTG+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16062DTG+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16062DTG+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16072RS20D0+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16074RS18D2+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16074RS18D3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16074RS19D2+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16074RS19D3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16125WTCS16+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16125WTCS16+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16125WTDA00+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16125WTDA00+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16125WTEJ00+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX167CC/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16826AGJ/VY+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16826AGJ/VY+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16903RA33/V+CE	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16903RA33/V+TCE	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16903SA50/V+CJ	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16903SA50/V+TCJ	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16920BATJS/V+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16922ATPC/V+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16922ATPD/V+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16922ATPD/V+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16922AUPA/V+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16922AUPA/V+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16922AUPB/V+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16922AUPC/V+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16922AUPC/V+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16922AUPD/V+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16922AUPD/V+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16922AUPE/V+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16922AUPE/V+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16922AUPF/V+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16922AUPF/V+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16922AUPG/V+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-May-2018

Discontinuance	MAX16922AUPG/V+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16922AUPH/V+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16924ATMA/V+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX16924ATMA/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX16924GGM/VS+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16924GGM/VS+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16929GUI/V+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16929GUI/V+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16930AGLW/VY+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX16930AGLW/VY+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX16930ALS/VY+CM7	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX16930ALS/VY+CM8	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX16930ATLT/V+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16930ATLT/V+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16993AGJL/V+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX16999AUA06+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16999AUA06+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16999AUA11+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16999AUA11+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16999AUA13+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16999AUA13+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16999AUA18+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16999AUA18+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16999AUA25+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX16999AUA25+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX17501EAUD+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX17502MATB+	MAX17502FATB+	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX17502MATB+T	MAX17502FATB+T	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX17502MEVAL#	MAX17502FTEVKIT#	24-Apr-2018	24-Apr-2018	EVKIT is No Longer Supported
Discontinuance	MAX17535ETG+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX17535ETG+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX17542IATB+	MAX17542GATB+	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX17542IATB+T	MAX17542GATB+T	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX187BC/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX189BC/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX191BC/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-May-2018

Discontinuance	MAX195BC/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX1963AETT250+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX1963AEZT110+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX1963AEZT300+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX1976AETT100+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX1976AETT100+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX1976AETT160+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX1976AETT160+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX1976AEZT300+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX1976AEZT300+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX20001ETE+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20001ETE+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20002DATPA/V+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20002DATPA/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20003CATPA/VY+	MAX20003DATPA/VY+	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20003CATPA/VY+T	MAX20003DATPA/VY+T	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20003CATPB/VY+T	MAX20003DATPB/VY+T	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20003DATPA/V+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20003DATPA/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20004AFDA/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20004AFDB/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20004AFDC/V+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20004AFDC/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20004AFDD/V+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20004AFDD/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20006AFDA/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20006AFDB/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20006AFDBA/V+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20006AFDBA/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20006AFDBB/V+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20006AFDBB/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20006AFDBC/V+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20006AFDBC/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20006AFDC/V+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20006AFDC/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20006AFDCA/V+	N/A	24-Apr-2018	24-Apr-2018	The part was not released

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-May-2018

Discontinuance	MAX20006AFDCA/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20006AFDCB/V+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20006AFDCB/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20006AFDD/V+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20006AFDD/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20008AFDA/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20008AFDB/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20008AFDC/V+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20008AFDC/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20008AFDD/V+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20008AFDD/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20010ATPI/V+T	MAX16995ATPI/V+T	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20010CATPC/V+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20010CATPC/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20030ATJA/VY+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20030ATJA/VY+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20048ATG/V+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20048ATG/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20048ATG/VY+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20048ATG/VY+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20049ATEAX/VY+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20049ATEAX/VY+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20098ATE/V+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20098ATE/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20098ATEA/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20098ATEB/V+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20098ATEB/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20098ATEC/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20098ATED/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20419ATGX/V+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20419ATGX/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20489ATJBX/V+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20489ATJBX/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20490AFBA/V+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20490AFBA/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX20490EVKIT#	N/A	24-Apr-2018	24-Apr-2018	EVKIT is No Longer Supported

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-May-2018

Discontinuance	MAX206C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX234C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX238C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX24025BIMP+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX24027ETU+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX244C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX248C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX250EJD	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX251EJD	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX2620E/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX263BC/D	MAX263AEWI+	24-Apr-2018	24-Apr-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX275BC/D	MAX275AEWP+	24-Apr-2018	24-Apr-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX295C/D	MAX295ESA+	24-Apr-2018	24-Apr-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX3108AEWA+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX310C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX3225CTP+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX323C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX325C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX326C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX327C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX329C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX334C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX3391EETD+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX3391EETD+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX3393EEBC+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX3486C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX350C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX359C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX3680EAI+TG05	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX3690ECJ+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX3885ECB+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX3885ECB+DG126	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX3885ECB+TDG002	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX391C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX392C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX3966C/D	N/A	24-Apr-2018	24-Apr-2018	Part is leaded. Request information on lead-free version

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-May-2018

Discontinuance	MAX397C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX398C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX399C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX4039ETB+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX4052C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX4053AC/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX4127C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX4210AETT+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX44260SAYT+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX4643ETA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX4685ETB+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX4685ETB+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX4731EBL+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX4731EBL+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX4745HELB+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX4840AELT+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX4840AELT+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX4908EBC+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX4908EBC+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX492C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX500BC/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX5096BAUP+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX5150ACPE+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX518BC/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX519BC/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX521BC/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX525BC/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX538BC/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX543BC/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX5490TB05000+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX5491SB03200+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX550AC/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX561C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX5880DUXF+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX5880DUXF+W	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX5880LUXF+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-May-2018

Discontinuance	MAX5880LUXF+W	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX5902LCETT+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX5902LCETT+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6307UK35D3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6307UK44D3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6310EUK46D3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6310EUK46D3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6310UK40D2+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6316LUK25CY+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX631AC/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6320PUK29BX+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6320PUK29BX+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6320PUK29DX+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6320PUK29DX+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6320PUK31CY+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6320PUK45CY+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6320PUK45CY+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6323FUT46+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6323GUT29+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6324CUT23+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6324CUT23+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6324CUT31+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6324DUT26+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6329VPUT+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6329WHUT+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6329WPUT+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6329ZPUT+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX632AC/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6331SUR+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX633BC/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6340UK16+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6340UK32+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX634C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6351SVUT+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6351SVUT+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6351UVUT+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-May-2018

Discontinuance	MAX6376XR31+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6376XR31+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6379XR37+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6379XR37+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6381LT18D3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6381LT18D3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6381LT18D5+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6381LT18D5+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6381LT26D2+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6381LT26D2+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6383LT16D1+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6383LT16D1+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6383LT25D3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6383LT25D3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6383LT44D3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6383LT44D3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6385XS31D1+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6385XS31D1+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6385XS36D5+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6385XS46D3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6385XS46D3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6386LT16D3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6386LT22D3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6386LT23D3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6386LT26D3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6386LT28D7+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6386LT31D3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6386LT44D3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6386LT44D3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6386LT46D3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6389LT27D3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6389LT27D3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX638AC/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6391KA17+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6391KA22+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6391KA23+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-May-2018

Discontinuance	MAX6391KA44+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6397VATA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6397WATA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6397YATA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6397ZATA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX639C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6408BS22+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6408BS22+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX640C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6411BS45+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6411BS45+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6419UK18+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6419UK18+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX641AC/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6425UK33+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6425UK33+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6426UK22+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6426UK22+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6426UK26+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6426UK29+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6426UK29+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6426UK46+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6426UK46+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX642AC/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6430DHUS+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6430EHUS+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6430EIUS+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6430MRUS+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6430ORUS+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6431MRUS+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6431ORUS+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6439UTEHRD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6443US16L+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6444US23K+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6444US31L+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6445UK16L+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-May-2018

Discontinuance	MAX6445UK23L+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6445UK26L+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6445UK46L+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6448UK46L+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6448UK46L+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6450UT26L+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6450UT29L+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6450UT46L+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6450UT46L+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6451UT26L+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6451UT46L+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6452UT26L+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6453UT16S+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6453UT26S+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6453UT26S+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6453UT46S+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6455UT29K+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6462UR19+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6462UR26+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6462XR46+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6465XR16+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6465XR46+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6465XR46+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6469TA15BD3+	N/A	01-Sep-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6469TA15BD3+T	N/A	01-Sep-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6469TA25BD3+	N/A	01-Sep-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6469TA25BD3+T	N/A	01-Sep-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6469TA30BD3+	N/A	01-Sep-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6469TA30BD3+T	N/A	01-Sep-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6470TA18AD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6470TA18AD3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6470TA25BD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6470TA25BD3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6470TA33AD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6470TA33AD3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6471TA15AD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-May-2018

Discontinuance	MAX6475TA25BD3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6475TA33AD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6475TA33AD3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6476TA15BD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6476TA15BD3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6476TA18AD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6476TA18AD3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6505UTP025+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6505UTP105+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6505UTP105+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6505UTP120+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6505UTP125+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6506UTP050+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6506UTP080+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6515UKP015+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6515UKP055+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6515UKP055+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6648YMUA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6648YMUA+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6702ALKA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6702ARKA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6702ASKA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6702AZKA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6702AZKA+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6702MKA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6702RKA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6702SKA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6702ZKA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6702ZKA+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6704YKA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6705AZKA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6706ALKA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6706ARKA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6706ASKA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6706AZKA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6706AZKA+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-May-2018

Discontinuance	MAX6712TEXS+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6712TEXS+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6715AUTSHD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6716UTYHD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6717UKWGD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6718AUKTID1+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6718AUKTID4+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6718AUKTID5+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6718AUKTID6+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6720UTZGD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6721UTVHD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6721UTYHD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6721UTZGD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6722AUTSDD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6722AUTSDD3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6729AKASVD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6729AKASVD3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6729AKAVHD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6729KARVD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6729KASHD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6729KASVD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6729KASYD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6729KATGD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6729KAWGD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6729KAYDD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6729KAYHD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6729KAZED3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6729KAZGD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6729KAZGD3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6729KAZWD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6730AUTSD4+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6730AUTSD4+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6730UTVD3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6731AUTLD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6732AUTSHD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6732AUTWGD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-May-2018

Discontinuance	MAX6732UTTGD3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6733AUTSHD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6734AKALTD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6734AKALTD3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6734AKASHD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6734AKASHD3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6734AKASYD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6734AKASYD3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6735AKALTD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6735AKALTD3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6735AKAYHD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6735KARVD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6735KASHD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6743XKRVD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6750KA16+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6750KA26+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6750KA31+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6750KA31+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6750KA46+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6750KA46+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6752KA16+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6752KA16+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6752KA23+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6752KA26+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6755UKLD0+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6755UKWD0+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6755UKZD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6759UTZD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6759UTZD3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6759UTZD3/V+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX6760TALAD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6760TALTD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6760TATZD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6760TAWAD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6760TAWED3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6760TAZWD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-May-2018

Discontinuance	MAX6761TALTD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6761TARAD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6761TATAD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6761TATZD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6761TAWED3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6761TAZWD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6765TTSD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6767TALD4+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6768TALD2+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6770TALD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6770TASD2+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6770TAYD2+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6770TAZD3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6771TASD2+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6773BTALD2+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6773BTALD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6773TALD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6773TASD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6774BTALD2+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6774BTALD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6774BTASD2+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6774TALD2+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6774TAYD4+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6776LTC+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6779LTA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6792TPSD1+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6792TPWD2+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6793TPTD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6795TPLD1+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6795TPLD1+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6795TPTD4+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6795TPWD2+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6796TPLD0+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6801UR44D2+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6801UR44D2+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6803US26D3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-May-2018

Discontinuance	MAX6830YHUT+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6830YHUT+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6830ZWUT+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6833FXRD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6833FXRD3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6833HXR3D3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6843UKD0+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6843UKD0+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6846KAZD3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6854UK45D1+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6856UK19D3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6860UK16D3+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6860UK16D3+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6862UK17+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6862UK225+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6862UK32+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6862UK32+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6862UK33+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6862UK33+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6864UK16D1L+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6864UK16D1L+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6864UK18D3S+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6864UK18D3S+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6864UK29D1S+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6864UK29D1S+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6866UK33D6S+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6866UK46D3S+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6866UK46D3S+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6869UK23D3S+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6869UK23D3S+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6869UK31D3S+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6887JETE+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6887KETE+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6896PAZT+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6896PAZT+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6899PAZT+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-May-2018

Discontinuance	MAX6899PAZT+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX694EJA	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX695C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6961AMH+D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6967ATE+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6967ATE+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6977AUE+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX6977AUE+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX706PEUA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX708SMJA	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX710C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX7231CFI/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX7375AXR485+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX7645BC/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX771C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX792RCSE+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX801MCPA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX801MEPA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX801MESA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX801NEPA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX802LEPA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX802MEPA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX802REPA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX802SCPA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX802SEPA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX802TEPA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX804REPA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX804RESA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX804SEPA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX804SESA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX804TEPA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX805RCPA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX805RCSA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX805REPA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX805RESA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX805SEPA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-May-2018

Discontinuance	MAX805SESA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX806REPA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX806RESA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX806SCPA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX806SEPA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX820LEPE+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX820MCPE+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX820MEPE+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX820RCPE+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX820RCSE+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX820REPE+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX820RESE+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX820SCPE+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX820TCPE+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8213AEJE	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8520ATP/V+	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX8520ATP/V+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAX8559ETA8A+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8559ETA8A+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8559ETAM1+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8559ETAM1+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8561ETA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8561ETA+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8569BETT30+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8630XETD15+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8630XETD15+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8630YETD20+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8630YETD20+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8630ZETD25+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8630ZETD25+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8633ELA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8633ELA+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8640ZEXT12+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8640ZEXT12+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8640ZEXT13+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8640ZEXT15+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-May-2018

Discontinuance	MAX8667ETEAB+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8667ETEAB+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8667ETEHR+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8667ETEHR+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8805WEWEAA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8805WEWEAA+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8805YEWEBG+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8805YEWEBG+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8805YEWEEE+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8805ZEWEAA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8805ZEWEAA+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8805ZEWEAD+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8805ZEWEAD+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8805ZEWEDD+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8805ZEWEDD+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8805ZEWEED+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8805ZEWEED+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8805ZEWEED+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8805ZEWEED+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8836ZEWEED+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8836ZEWEED+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8840ELT21+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8840EYT27+TG65	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8867EZK50+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8867EZK50+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8893AEWV+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8893AEWV+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8893BEWV+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8893BEWV+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8952AEWE+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8952BEWE+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX8952BEWE+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX907C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX9276GGN+T	MAX9276AGGN/VY+T	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX9276GGN/VY+T	MAX9276AGGN/VY+T	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX9320EKA+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX9320EKA+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX942C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-May-2018

Discontinuance	MAX951C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX954C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAX9720BEUE+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAXQ610J-2548+T	N/A	24-Apr-2018	24-Apr-2018	The part was not released
Discontinuance	MAXQ614V-2541+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAXQ614V-L001+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAXQ614V-L002+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MAXQ616V-2581+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MX7225K/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MX7537TE	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MX7582K/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MX7672K/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MX7847J/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MXD1210C/D	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MXD1811XR41+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MXD1811XR41+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MXD1811XR44+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MXD1811XR44+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MXD1816UR22+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MXD1816UR23+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MXD1816XR23+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MXD1816XR26+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MXD1816XR31+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MXD1816XR31+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MXD1817UR22+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MXD1817UR23+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MXD1817UR26+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MXD1817XR22+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MXD1817XR23+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MXD1817XR26+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MXD1817XR29+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MXD1817XR31+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MXD1818UR23+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MXD1818UR23+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MXD1818XR22+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	MXD1818XR23+	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 25-May-2018

Discontinuance	MXD1818XR23+T	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	TSC426C/D	N/A	24-Apr-2018	24-Apr-2018	Part is leaded. Request information on lead-free version
Discontinuance	VT8020FQ	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	VT8020FQR	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	VT8020FQX	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	VT8024FQ	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	VT8024FQR	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured
Discontinuance	VT8024FQX	N/A	24-Apr-2018	24-Apr-2018	Part can no longer be manufactured