



Product Change Notice

PCN Number: 15-0936-02
Issue Date: 29-JULY-2016

Exar Corporation

www.exar.com | Support: customersupport@exar.com

PRODUCTS AFFECTED:	ST16C654CQ100-F	ST16C654CQ100TR-F	ST16C654IQ100-F	ST16C654IQ100TR-F
	XR16C854CQ-F	XR16C854CQTR-F	XR16C854IQ-F	XR16C854IQTR-F
	XR16C864CQ-F	XR16C864CQTR-F	XR16C864IQ-F	XR16C864IQTR-F
	XR16L788CQ-F	XR16L788CQTR-F	XR16L788IQ-F	XR16L788IQTR-F
	XR16M598IQ100-F	XR16M598IQ100TR-F	XR16M654IQ100-F	XR16M654IQ100TR-F
	XR16V598IQ100-F	XR16V654IQ-F	XR16V654IQTR-F	XR16V798IQ-F
	XR16V798IQTR-F	XRT91L32IQ-F	XRT91L32IQTR-F	

CHANGE CATEGORY:

<input type="checkbox"/> Material	<input type="checkbox"/> Process	<input type="checkbox"/> Package
<input type="checkbox"/> Design	<input type="checkbox"/> Datasheet	<input type="checkbox"/> Packing/Shipping
<input checked="" type="checkbox"/> Other: Alternate assembly subcon		

DESCRIPTION OF CHANGE:
Qualification of alternate assembly subcon, Greatek, Taiwan.

IMPACT OF CHANGE:
There is no change to product form, fit or function.

TARGET IMPLEMENTATION DATE: 31-OCTOBER-2016

Please contact customer support (customersupport@exar.com) for sample date availability or qualification data

PROPRIETARY INFORMATION
THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.